Abstract

Component Attachments

A printer vacuum guide member of plastics material, attached to a printer chassis of

metal so as to allow thermal movements, has flexible limbs which extend from walls near
the ends of the member to attachment points for receiving fixing screws. The member is
fixedly attached to the chassis at points at a central location. To further reduce the
effects of thermal expansion, the guide member may be sub-divided into separate
component parts along its length.